

- May 12<sup>th</sup> chlorine pump temporary overfeed.



- May 24th flow testing of Willow Wood well
- May 27th clogged injection line flushed

